

Turbos - TUR0347 - TURBO INTERCAMBIO 53269700000

Turbo reparado nuevo BMW 535D Biturbo 53269700000 53269710000 53269880000 54399700045
54399710045 54399880045

R2S K26+KP39 TwinTurbo

53269700000+54399700045+59001030100 53269880000+54399880045+59001030100

53269700000 53269710000 53269880000 54399700045 54399710045 54399880045

5326-970-0000 5326-971-0000 5326-988-0000 5439-970-0045

5439-971-0045 5439-988-0045

5326 970 0000 / 5326 971 0000

5326 988 0000 / 5439 970 0045

5439 971 0045 / 5439 988 0045

126419700000 126419880000 11657794571 11657794572 7793403AI02 7793402AI03

11657793402AI03 11654715774AI01 7793402-07 4715774AI01

BMW 535D (E60/E61) BiTurbo [Jan 2004 .. Mar 2007]

