

Turbos - TUR0489 - TURBO INTERCAMBIO 753546-14

Referencias

753546

753546-0014

753546-0023

753546-5014S

753546-5023S

753546-9023S

Específicas Land-Rover

6G9Q6K682CA

6G9Q6K682CB

LR003578

LR006862

9684856680

Land Rover

Land Rover Freelander 2 FA_ 2.2 TD4 4x4 2006/10-2014/10 2179 ccm, 110 KW, 150 PS

Land Rover Freelander 2 FA_ 2.2 TD4 4x4 2007/01-2014/10 2179 ccm, 112 KW, 152 PS

Land Rover Freelander 2 FA_ 2.2 TD4 4x4 2006/10-2014/10 2179 ccm, 115 KW, 156 PS

Land Rover Freelander 2 FA_ 2.2 TD4 4x4 2006/10-2014/10 2179 ccm, 118 KW, 160 PS



INGENIERIA F&M S.A. 1997
6032-KR08-CA 11/17A
755546-14 art KJR041071

761963-1

MW 009 483