

Turbos - TUR0751 - TURBO INTERCAMBIO 10009700162, 16389700015

10009700111, 10009700150, 10009700162, 10009700178, 10009700218, 10009700331, 10009700335, 16389700015, 18539700022, 16389700021, 18539700041, 18539700071, 16389980021, 10009980331, 1000-970-0111, 100

1Volvo

Volvo S60 II 2015/03-2018/05 134 2.0 D5 1969 ccm, 165 KW, 224 PS

Volvo S60 II 2015/03-2018/05 134 D5 Drive-E Polestar 1969 ccm, 171 KW, 232 PS

Volvo S90 II 2016/03-2022/12 234 2.0 D5 AWD 1969 ccm, 173 KW, 235 PS

Volvo S90 II 2019/06-2022/12 234 2.0 D5 Polestar AWD 1969 ccm, 177 KW, 240 PS

Volvo V60 I 2015/03-2018/05 155, 157 D5 1969 ccm, 165 KW, 224 PS

Volvo V90 II Kombi 2016/03-2022/12 235, 236 2.0 D5 AWD 1969 ccm, 173 KW, 235 PS

Volvo V90 II Kombi 2016/10-2022/12 235, 236 2.0 Polestar AWD 1969 ccm, 176 KW, 239 PS

Volvo XC60 II 2017/03-2022/12 246 2.0 D5 AWD 1969 ccm, 173 KW, 235 PS

Volvo XC60 II 2018/10-2022/12 246 2.0 D5 Polestar AWD 1969 ccm, 177 KW, 240 PS

Volvo XC90 II 2018/10-2022/12 256 2.0 D5 Polestar AWD 1969 ccm, 177 KW, 240 PS

Volvo XC90 II 2015/10-2018/12 256 D4 AWD 1969 ccm, 140 KW, 190 PS

Volvo XC90 II 2016/03-2019/12 256 D5 AWD 1969 ccm, 173 KW, 235 PS

Volvo XC90 II 2014/09-2016/12 256 D5 AWD 1969 ccm, 165 KW, 224 PS

Volvo XC90 II 2016/03-2022/12 256 D5 Drive Polestar AWD 1969 ccm, 176 KW, 239 PS

