

Turbos - TUR0593 - TURBO INTERCAMBIO 818988, 817088, 802452, 817082

03L145721A, 03L145721AV, 03L145721AX, 03L145721C, 03L145721Cx, 03L145701T, 03L145701TX

Referencia del fabricante

817081-0001, 817081-1, 817081-5001S, 818988-0001, 818988-1, 818988-5001S, 802452-

03L145721A, 03L145721AV, 03L145721AX, 03L145721C, 03L145721Cx, 03L145701T, 03L145701TX

Referencia del fabricante

817081-0001, 817081-1, 817081-5001S, 818988-0001, 818988-1, 818988-5001S, 802452-5004S, 802452-0004, 802452-4, 818988-5002S, 818988-0002, 818988-2

