

Turbos - TUR0061 - TURBO SEMINUEVO 452055-4

Turbo reparado, reconstruido, nuevo, economico, barato, land rover defender, discovery, range rover 2.5 tdi, 452055-4, 452055-8, 4520554.

Land-Rover Defender 2.5 TDI 126 CV |

Land-Rover Discovery I 2.5 TDI 113 CV |

Land-Rover Discovery I 2.5 TDI 126 CV |

Land-Rover Range Rover 2.5 TDI 113 CV |

Land-Rover Range Rover 2.5 TDI 126 CV 452055-0004 | 452055-0007 |

452055-0008 | 452055-4 |

452055-7 | 452055-8 |

452055-5004S | 452055-5007S |

452055-5008S | PMF100510 |

ERR4802 | ERR4893

