

Turbos - TUR0151VAL - TURBO INTERCAMBIO CON VALVULA ELECTRONICA BMW 49135-05750

Turbo reconstruido o reparado con valvula electronica bmw 118d 318d 4913505710, 4913505711, 4913505720, 4913505730, 4913505740, 4913505750, 4913505760, 4913505761, 49135-05710, 49135-05711, 49135-0572

49S3505761RS, 4913505710, 4913505711, 4913505720, 4913505730, 4913505740, 4913505750, 4913505760, 4913505761, 49135-05710, 49135-05711, 49135-05720, 49135-05730, 49135-05740, 49135-05750, 49135-05760, 49135-05761, 49S35-05761, 49E9035208, 49E90-35208, 49S3505761 11654716165, 11657795496, 11657795497, 11657795798, 11657795798F, 4716165, 7795496, 7795497, 7795798, 7795798F

BMW

118d

1.9 90/110 2006 - 2012 N47D20A, N47D20C, E81, E82, E88, E87, M47TU2D20

BMW

318d

1.9 90/110 2005 - 2007 E90, E91, M47N204D4

