

Turbos - TUR0708 - TURBO INTERCAMBIO 788479

788479-5006S, 788479-5003S, 788479-3, 788479-0003, 788479-0006, 788479-6

Referencias OEM

BH1Q6K682CB, BH1Q6K682CA, BH1Q-6K682-CA, BH1Q-6K682-CB, LR042752, LR029972, LR012858, LR004821, LR006869,

788479-5006S, 788479-5003S, 788479-3, 788479-0003, 788479-0006, 788479-6

Referencias OEM

BH1Q6K682CB, BH1Q6K682CA, BH1Q-6K682-CA, BH1Q-6K682-CB, LR042752, LR029972, LR012858, LR004821, LR006869, LR008203, LR01010138, LR018497, LR00596, LR83

Indicación del vehículo

Land Rover Defender 90 110 130 2006-2016 2.2D 122cv

