

Turbos - TUR0155 - TURBO SEMINUEVO 452098-2

Turbo reparado o intercambio Honda o Rover 200 SDI, 452098-2 452098-4

Referencias

452098

452098-0002

452098-0004

Específicas de Honda

PMF100440

PMF6105

Vehículos compatibles

Honda

Civic 2.0 i TDI (motor 20T2N/TCI/E)

Rover

200 SDI (motor 20T2N/TCI/E)

220 SDI (motor 20T2N/TCI/E)

420 SDI (motor 20T2N/TCI/E)

600 SDI (motor 20T2N/TCI/E)

620 SDI (motor 20T2N/TCI/E)

