

Turbos - TUR0288 - TURBO REPARADO KIA SORENTO 2.5 CRDI 53039700144

28200-4A470, 282004A470

28200-4A470FF, 282004A470FF

KKK Nr.

BV43-0122, BV43-0144

53039880144, 53039700144, 53039710144

53039880122, 53039700122, 53039710122

Hyundai

Hyundai H-1 Cargo 2.5 CRDi 2008/02-2016/12 2497 ccm, 120 KW, 163 PS

Hyundai H-1 Cargo 2.5 CRDi 2008/02-2016/12 2497 ccm, 125 KW, 170 PS

Hyundai H-1 Cargo 2.5 CRDi 2009/08-2016/12 2497 ccm, 100 KW, 136 PS

Hyundai H-1 Travel 2.5 CRDi 2008/05-2016/12 2497 ccm, 120 KW, 163 PS

Hyundai H-1 Travel 2.5 CRDi 2008/05-2016/12 2497 ccm, 125 KW, 170 PS

Hyundai H-1 Travel 2.5 CRDi 2008/07-2016/12 2497 ccm, 100 KW, 136 PS

Kia

KIA Sorento I JC 2.5 CRDi 2002/08-2016/12 2497 ccm, 103 KW, 140 PS

KIA Sorento I JC 2.5 CRDi 2006/05-2016/12 2497 ccm, 120 KW, 163 PS

KIA Sorento I JC 2.5 CRDi 2006/12-2016/12 2497 ccm, 125 KW, 170 PS

