

Turbos - TUR0305 - TURBO INTERCAMBIO HYUNDAI STAREX 2.5 TD 53039700143

Turbo nuevo reconstruido barato Hyundai Starex 2.5 TD 53039700126, 53039700143, 53039880126, 53039880143, 5303-970-0126, 5303-970-0143, 5303-988-0126, 5303-988-0143, 53039880143RS

HYUNDAI

Starex

2.5 103/120 2002 - 2007 H-1, A1, D6A, D4CB, Cargo, Travel, 4WD

OE

282004A450, 28200-4A450

53039700126, 53039700143, 53039880126, 53039880143, 5303-970-0126, 5303-970-0143, 5303-988-0126, 5303-988-0143, 53039880143RS

53039700126

53039700143

53039880126

53039880143

5303 970 0126

5303 970 0143

5303 988 0126

5303 988 0143

28200-4A450

282004A450



