

Turbos - TUR0317 - TURBO CON VALVULA ELECTRONICA 49335-00585

Turbo reparado intercambio nuevo BMW 120D 320D 520D X1 2.0D 4933500500, 4933500510, 4933500511, 4933500520, 4933500521, 4933500530, 4933500531, 4933500550, 4933500560

BMW

120d

2.0 120/135 2010 F20, F21, 2D, N47TUEOL

BMW

320d

2.0 120/135 2005 N47D20, E90N, E91N, E92N, E93N, F30, F31

BMW

520d

2.0 120/135 2010 N47D20, F07, F10, F11, GT

BMW

X1

2.0 120/135 2010 N47D20, E84

BMW

X3

2.0 120/135 2010 N47D20, F25

11657808758, 11658506721, 11658512464, 11658512465, 11658515187, 11658515188, 11658519477, 11658519478, 7808758, 8506721, 8512464, 8512465, 8513298, 8515187, 8515188, 8519477, 8519478, 11652365501, 8513299, 11658513298, 11658513299

4933500500, 4933500510, 4933500511, 4933500520, 4933500521, 4933500530, 4933500531, 4933500550, 4933500560, 4933500561, 4933500570, 49335-00500, 49335-00510, 49335-00511, 49335-00520, 49335-00521, 49335-00530, 49335-00531, 49335-00550, 49335-00560, 49335-00561, 49335-00570, 49335-00581, 49335-00582, 49335-00583, 49335-00584, 49335-00585, 4933500581, 4933500582, 4933500583, 4933500584, 4933500585, 4933500585RS

