

Turbos - TUR0569 - TURBO INTERCAMBIO 812971, 798166, 853333

1717629, 1720418, 1762066, 1857660, BK3Q6K682AB, BK3Q6K682AC, BK3Q6K682RB, BK3Q6K682RC

Fabricantes

798166-0007, 798166-5007S, 812971-0002, 812971-0006, 812971-5002S, 812971-5006S

1717629, 1720418, 1762066, 1857660, BK3Q6K682AB, BK3Q6K682AC, BK3Q6K682RB, BK3Q6K682RC

Fabricantes

798166-0007, 798166-5007S, 812971-0002, 812971-0006, 812971-5002S, 812971-5006S

Indicación del vehículo

FORD RANGER 3.2 TDCI 20V 200 CV de 2011

Ford OE Nr.

1857660 2231172 1720418 1717629

BK3Q6K682RB BK3Q-6K682-RB

BK3Q6K682AC BK3Q-6K682-AC

BK3Q6K682EA BK3Q-6K682-EA

RMBK3Q6K682AC RMBK3Q-6K682-AC

Garrett OEM Nr.

798166-5007S 798166-0007 798166-7

812971-5002S 812971-0002 812971-2

812971-5006S 812971-0006 812971-6

853333-5001S 853333-0001 853333-1 853333-5001W

