

Turbos - TUR0817 - PARTE BI- TURBO 824756

LR092675 LR116631 LR062000

FPLA-6K682-CE FPLA6K682CE

FPLA-6K682-CD FPLA6K682CD

FPLA-6K682-CC FPLA6K682CC

Garrett OEM Nr.

824756-5006S 824756-6 824756-0006

824756-5005S 824756-5 8

Land / Range Rover

Land Rover Discovery IV 2009/11-2018/12 L319 3.0 SDV6 4x4 2993 ccm, 188 KW, 256 PS

Land Rover Discovery IV 2009/09-2016/12 L319 3.0 TD 4x4 2993 ccm, 180 KW, 245 PS

Land Rover Discovery IV 2010/05-2018/12 L319 3.0 TD 4x4 2993 ccm, 155 KW, 211 PS

Land Rover Discovery IV 2012/07-2016/12 L319 3.0 TD 4x4 2993 ccm, 183 KW, 249 PS

Land Rover Discovery IV Van 2011/01-2017/12 L319 3.0 TD 4x4 2993 ccm, 155 KW, 211 PS

Land Rover Discovery IV Van 2011/01-2017/12 L319 3.0 TD 4x4 2993 ccm, 180 KW, 245 PS

Land Rover Discovery IV Van 2011/01-2017/12 L319 3.0 TD 4x4 2993 ccm, 188 KW, 256 PS

Land Rover Range Rover Sport 2014/12-2017/12 L494 3.0 SDV6 Hybrid 4x4 2993 ccm, 215 KW, 292 PS

Land Rover Range Rover Sport 2015/06-2017/12 L494 3.0 SDV6 Hybrid 4x4 2993 ccm, 225 KW, 306 PS

Land Rover Range Rover Sport 2013/04-2018/12 L494 3.0 TDV6 4x4 2993 ccm, 155 KW, 211 PS

Land Rover Range Rover Sport 2013/04-2021/12 L494 3.0 TDV6 4x4 2993 ccm, 190 KW, 258 PS

teilen

