

## Turbos - TUR0047N - TURBO NUEVO 706977

706977-0001, 706977-0002, 706977-0003, 706977-1, 706977-2, 706977-3, 53039700009, 53039800009, 53039880009, 53039900009, F400002, RHF4VVP1, VVP1,

Indicación del vehículo

Citroen

Berlingo 2.0

706977-0001, 706977-0002, 706977-0003, 706977-1, 706977-2, 706977-3, 53039700009, 53039800009, 53039880009, 53039900009, F400002, RHF4VVP1, VVP1,

Indicación del vehículo

Citroen

Berlingo 2.0 HDI 90 de 1996

C5 2.0 HDI 90 de 2001

Evasión 2.0 HDI 110 de 1998

Jumpy 2.0 HDI 109 110 desde 1995

PICASSO 2.0 HDI 90 de 1999

SYNERGIE 2.0 HDI 109 desde 1998

Xantia 2 2.0 HDI 90 de 1997

Xsara 2.0 HDI 90 de 1998

Xsara PHASE 2 2.0 HDI 90 de 2000

Xsara PICASSO 2.0 HDI 90 de 1999

Fiat

Scudo 2.0 JTD 95 de 1995

Ulises 2 2.0 JTD 107 109 de 2002

Ulises 2.0 JTD 107 109 de 1998

Lancia

Phedra 2.0 JTD 110 de 2001

Zeta 2.0 HDI 108 de 2001

Peugeot

206 2.0 HDI 90 de 1998

306 2.0 HDI 90 de 1998

307 2.0 HDI 90 de 2001  
PHASE 2 2.0 HDI 90 de 2005  
307 SW 2.0 HDI 90 de 2002  
406 2.0 HDI 90 de 1999  
806 2.0 HDI 109 desde 1998  
Boxer 2.0 HDI 108 de 1999  
Experto 2.0 HDI 95 de 1995  
Partner 2.0 HDI 90 de 2002



