

Turbos - TUR0315N - TURBO ****NUEVO**** 53049700115

Land Rover OEM

4H2Q6K682CB 4H2Q-6K682-CB
4H2Q6K682CD 4H2Q-6K682-CD
4H2Q6K682CF 4H2Q-6K682-CF
4H2Q6K682CG 4H2Q-6K682-CG
4H2Q6K682CH 4H2Q-6K682-CH
4H2Q6K682CJ 4H2Q-6K682-CJ
4H2Q6K682CL 4H2Q-6K682-CL
4H2Q6K682DB 4H2Q-6K682-DB
RM4H2Q6K682CG RM4H2Q-6K682-CG

LR021637 LR008838 LR006422
LR005954 LR003356 LR004286
LR005846 LR010188 LR021042

4H206K682CF 4H2Q9T428AB 4H206K682CB 1334916 1354257 1357581

Borg Warner KKK OEM

53049700039 53049880039 53049900039
53049700065 53049880065 53049900065
53049700069 53049880069 53049900069
53049700115 53049880115 53049900115
53049700116 53049880116 53049900116

BV50-039 BV50-065 BV50-069 K04-0115 K04-0116