

Turbos - TUR0054 - TURBO SEMINUEVO 708366-1

Turbo reparado, nuevo, reconstruido, barato, economico, Land Rover Freelander 2.0 Td4 (L314) [2000 .. 2006], 708366-0003 708366-0002 708366-0001

Turbocompresor 708366-0001 708366-1 7781450B de Land Rover Freelander 2.0 Td4
Turbo totalmente reacondicionado. Turbocompresor Garrett genuino, reconstruido, reconstruido y remanufacturado.

708366-5007S 708366-9007S 708366-5005S 708366-9005S

708366-0003 708366-0002 708366-0001

708366-3 708366-2 708366-1

7781450B STC4546 LR006108

GT1749V

Land Rover Freelander 2.0 Td4 (L314) [2000 .. 2006]

