

Turbos - TUR0567 - TURBO INTERCAMBIO 824168 282012A820

824168-1 824168-0001 824168-5001S
824168-2 824168-0002 824168-5002S

Kia / Hyundai OE Nr.

28201-2A810 282012A810

28201-2A810RM 282012A810RM

M28201-2A810 M282012A810

KIA

KIA Carens IV 2013/03-2020/12 -- 1.7 CRDi 1685 ccm, 100 KW, 136 PS

KIA Carens IV 2015/07-2020/12 -- 1.7 CRDi 1685 ccm, 104 KW, 141 PS

KIA Optima 2015/11-2020/12 -- 1.7 CRDi 1685 ccm, 104 KW, 141 PS

KIA Optima 2012/03-2020/12 -- 1.7 CRDi 1685 ccm, 100 KW, 136 PS

KIA Optima Sportswagon 2016/09-2020/12 JF 1.7 CRDi 1685 ccm, 104 KW, 141 PS

KIA Sportage 2016/11-2020/12 QL, QLE 1.7 CRDi 1685 ccm, 104 KW, 141 PS

HYUNDAI

Hyundai Sonata VII 2015/01-2020/12 LF 1.7 CRDi 1685 ccm, 104 KW, 141 PS

Hyundai Tucson 2015/06-2020/12 TL, TLE 1.7 CRDi 1685 ccm, 104 KW, 141 PS

Hyundai i40 2012/03-2020/12 VF 1.7 CRDi 1685 ccm, 100 KW, 136 PS

Hyundai i40 2015/01-2020/12 VF 1.7 CRDi 1685 ccm, 104 KW, 141 PS

Hyundai i40 CW 2015/01-2020/12 VF 1.7 CRDi 1685 ccm, 104 KW, 141 PS

Hyundai i40 CW 2011/07-2020/12 VF 1.7 CRDi 1685 ccm, 100 KW, 136 PS

