

Turbos - TUR0146 - TURBO CON VALVULA ELECTRONICA 49477-01214 49477-01204

LR022358 LR038309 LR038322

LR049592 LR065510 LR065511

Mitsubishi MHI OEM Nr.

4947701203 49477-01203

4947701204 49477-01204

4947701213 49477-01213

4947701214 49477-01214

49U77012

Freelander 2.2 SD4 (motor TD4)

Freelander 2.2 TD4 (motor TD4)

Jaguar

Jaguar XF _J05_, CC9 2.2 D 2011/04-2015/04 2179 ccm, 120 KW, 163 PS

Jaguar XF _J05_, CC9 2.2 D 2012/03-2015/04 2179 ccm, 147 KW, 200 PS

Jaguar XF _J05_, CC9 2.2 D 2011/05-2015/04 2179 ccm, 140 KW, 190 PS

Jaguar XF Sportbrake CC9 2.2 D 2012/09-2014/04 2179 ccm, 120 KW, 163 PS

Jaguar XF Sportbrake CC9 2.2 D 2012/09-2014/04 2179 ccm, 147 KW, 200 PS

Land Rover

Land Rover Discovery Sport LC 2.2 D 4WD 2014/12-2018/12 2179 ccm, 140 KW, 190 PS

Land Rover Discovery Sport LC 2.2 D 4WD 2014/12-2018/12 2179 ccm, 110 KW, 150 PS

Land Rover Freelander 2 FA_ 2.2 eD4 2010/08-2014/10 2179 ccm, 110 KW, 150 PS

Land Rover Freelander 2 FA_ 2.2 SD4 4x4 2010/08-2014/10 2179 ccm, 140 KW, 190 PS

Land Rover Freelander 2 FA_ 2.2 TD4 4x4 2006/10-2014/10 2179 ccm, 110 KW, 150 PS

Land Rover Freelander 2 FA_ 2.2 TD4 4x4 2006/10-2014/10 2179 ccm, 115 KW, 156 PS

Land Rover Freelander 2 FA_ 2.2 TD4 4x4 2007/01-2014/10 2179 ccm, 112 KW, 152 PS

Land Rover Freelander 2 LF_ 2.2 TD4 4x4 2006/10-2014/10 2179 ccm, 118 KW, 160 PS

Land Rover Range Rover Evoque LV 2.2 eD4 2011/06-2018/12 2179 ccm, 110 KW, 150 PS

Land Rover Range Rover Evoque LV 2.2 SD4 2011/06-2018/12 2179 ccm, 140 KW, 190 PS

Land Rover Range Rover Evoque LV 2.2 TD4 2011/06-2018/12 2179 ccm, 110 KW, 150 PS

