

Turbos - TUR0315 - TURBO REPARADO CON VALVULA LAND ROVER 53049700115

53049700039 53049880039 53049900039
53049700065 53049880065 53049900065
53049700069 53049880069 53049900069
53049700115 53049880115 53049900115
53049700116 53049880116 53049900116

Land Rover

Land Rover Discovery III TAA 2.7 TD 2004/07-2009/09 2720 ccm, 140 KW, 190 PS

Land Rover Discovery IV LA 2.7 TD ab 2009/09- 2720 ccm, 140 KW, 190 PS

Land Rover Range Rover Sport LS 2.7 TDVM ab 2005/02- 2720 ccm, 140 KW, 190 PS

