

Turbos - TUR0121 - TURBO CON VALVULA ELECTRONICA 54399700063, 54399700112

Turbo con valvula electronica Land Rover 3.6 turbo diesel, 54399700063, 54399700112, LR003668, LR004038, reparado, economico, nuevo, barato, economico.

54399700063

BV39-063

BV39-112

54399700063

54399700112

54399880063

54399880112

Específicas de Land-Rover

LR003668

LR004038

Turbo Land-Rover Rover 3.6 (TDV8 Sport) KKK 54399700063

Turbo motor 3.6 TDV8 272cv de 2005 a 2010

LR008827

LR021044

LR021654

