



Turbos - TUR0430N - TURBO NUEVO 54409700014

5440-970-0014, 54409700014, 5440-988-0014, 54409880014, A671090078080, 671090078080, 6710900780, A6710900780, 14209083DN

2011- SsangYong Actyon Sports I, II 2.0 Xdi

2012-SsangYong Rexton W 2.0 Xdi

2013- SsangYong Rodius II 2.0 Xdi

