

## Turbos - TUR0867 - TURBO INTERCAMBIO 54399700121

28200-4A470, 282004A470  
28200-4A470FF, 282004A470FF

N.º KKK  
BV43-0122, BV43-0144  
53039880144, 53039700144, 53039710144  
53039880122, 53039700122, 53039710122

### Hyundai

Hyundai H-1 Cargo 2.5 CRDi 02/2008-12/2016 2497 cc, 120 KW, 163 CV  
Hyundai H-1 Cargo 2.5 CRDi 02/2008-12/2016 2497 cc, 125 KW, 170 CV  
Hyundai H-1 Cargo 2.5 CRDi 08/2009-12/2016 2497 cc, 100 KW, 136 CV

Hyundai H-1 Travel 2.5 CRDi 05/2008-12/2016 2497 cc, 120 KW, 163 CV  
Hyundai H-1 Travel 2.5 CRDi 05/2008-12/2016 2497 cc, 125 KW, 170 CV  
Hyundai H-1 Travel 2.5 CRDi 07/2008-12/2016 2.497 cc, 100 KW, 136 CV

### Kia

Sorento I JC 2.5 CRDi 08/2002-12/2016 2.497 cc, 103 KW, 140 CV  
KIA Sorento I JC 2.5 CRDi 05/2006-12/2016 2.497 cc, 120 KW, 163 CV  
KIA Sorento I JC 2.5 CRDi 12/2006-12/2016 2.497 cc, 125 KW, 170 CV

