

Turbos - TUR0280 - TURBO INTERCAMBIO SUZUKI VITARA 734204-1

Turbo reparado reconstruido barato economico, Suzuki Vitara HDI, 734204-1 734204-0001, 13900-67G10
1390067G10 ZY34027402

Turbo Suzuki Vitara 16V HDI Garrett 734204

Turbo motor LHK96JG22 110cv desde 2002

Referencias

734204

734204-0001

734204-5001S

Específicas de Suzuki

13900-67G10

ZY34027402

