



Turbos - TUR0300 - TURBO RECONSTRUIDO VW TRANSPORTER 1.9 TD 54399700058

Turbo reparado intercambio nuevo VW Transporter 1.9 TD, 54399700058, 54399700084, 54399880058, 54399880084, 5439-970-0058, 5439-970-0084, 5439-988-0058, 5439-988-0084

VOLKSWAGEN

Commercial

1.9 62/75 2005 - 2008 Industrial, TDI, BRR, Euro4

VOLKSWAGEN

Transporter

1.9 62/75 2005 - 2009 TDI, T5, BRS, BRR, BRS, 7HM, 7HN, 7HF, 7EF, 7EM, 7EN, 7HA, 7HH, 7EA, 7EH, 7HB, 7HJ, 7EB, 7EJ, 7JD, 7JE

03G253010D, 03G253016G, 2X0253019A, 2X0253019B, 03G253010DV, 03G253010DX, 03G253016GV, 03G253016GX, 2X0253019, 2X0253019V, 2X0253019X

54399700058, 54399700084, 54399880058, 54399880084, 5439-970-0058, 5439-970-0084, 5439-988-0058, 5439-988-0084, 54399710058, 54399720058, 54399730058, KP39-58, 54399880058RS

