

Turbos - TUR0128 - TURBO SEMINUEVO 452239-6 land rover discovery 2.5 td5

Turbo reparado, nuevo, intercambio economico y barato, land rover discovery 2.5 td5, 452239-0003, 452239-0005, 452239-0006, 452239-0009, 452239-5008S, 452239-5009S

Land Rover

Land Rover Defender Cabrio 1998/06-2016/02 LD_ 2.5 TD5 4x4 2495 ccm, 90 KW, 122 PS

Land Rover Defender Pick-up 1998/06-2016/02 L316 2.5 TD5 4x4 2495 ccm, 90 KW, 122 PS

Land Rover Defender Station Wagon 1998/06-2016/02 L316 2.5 TD5 4x4 2495 ccm, 90 KW, 122 PS

Land Rover Discovery II 1998/11-2004/06 L318 2.5 TD5 4x4 2495 ccm, 102 KW, 139 PS

