

Turbos - TUR0291 - TURBO SEMINUEVO LAND ROVER RANGE ROVER 53169706701

Turbocompresor para Land-Rover Range Rover 2.4 TDI 110hp (1986-1990) 53169706701 turbo reparado
nuevo intercambio 5316 970 6701

Turbocompresor para Land-Rover Range Rover 2.4 TDI 110hp (1986-1990) 53169706701

35242015A, 35242015-A, k16-6701, 53169886701, 53169706701, 5316-988-6701, 5316-970-6701



