

Turbos - TUR0304 - TURBO RECONSTRUIDO VW TRANSPORTER 2.5 TDI 729325-2

Turbo reparado intercambio nuevo VW Transporter 2.5 TDI 729325-2, 729325-0002, 729325-3, 729325-0003, 729325-4, 729325-0004, 729325-5002S, 729325-5003S, 729325-5004S, 729325-9004S

VW

VW Multivan V 7HM, 7HN, 7HF, 7EF, 7EM, 7EN 2.5 TDI 2003/04-2009/11 2461 ccm, 96 KW, 130 PS

VW Multivan V 7HM, 7HN, 7HF, 7EF, 7EM, 7EN 2.5 TDI 4motion 2004/07-2009/11 2461 ccm, 96 KW, 130 PS

VW Transporter V Bus 7HB, 7HJ, 7EB, 7EJ, 7EF 2.5 TDI 2004/07-2009/11 2461 ccm, 96 KW, 130 PS

VW Transporter V Bus 7HB, 7HJ, 7EB, 7EJ, 7EF 2.5 TDI 4motion 2004/07-2009/11 2461 ccm, 96 KW, 130 PS

VW Transporter V Kasten 7HA, 7HH, 7EA, 7EH 2.5 TDI 2003/04-2009/11 2461 ccm, 96 KW, 130 PS

VW Transporter V Kasten 7HA, 7HH, 7EA, 7EH 2.5 TDI 4motion 2004/07-2009/11 2461 ccm, 96 KW, 130 PS

VW Transporter V Pritsche/Fahrgestell 7JD, 7JE, 7JL, 7JY, 7JZ, 2.5 TDI 2004/07-2009/11 2461 ccm, 96 KW, 130 PS

VW Transporter V Pritsche/Fahrgestell 7JD, 7JE, 7JL, 7JY, 7JZ, 2.5 TDI 4motion 2004/07-2009/11 2461 ccm, 96 KW, 130 PS

?

