



Turbos - TUR0313 - SUSTITUIDO POR TUR0532

Turbo reparado economico barato nuevo Mitsubishi Pajero 2.5 TD, 49377-03040 4937703040 49377-03043 4937703043 49377-03053 49377-034041

Turbo TD04 49377-03043 49377-03053 49377-03041 49377-03040 turbocompresor para MITSUBISHI PAJERO SHOGUN interrefrigerado 94-98 4M40 2.8L

