

Turbos - TUR0330 - TURBO INTERCAMBIO 53149706087

53149886087, 53149706087, 53149706082, 53149886082, 466534-0003, 466534-0005
068145704C, 068145702N, 068145702NX, 068145702NV, 068145702MX, 068145702CX, 068145702CV,
068145704C, 068145704F

VW 068145703QV; VW 068145702B; VW 068145703QX; VW 068145703M; VW 068145702BV; VW
068145704C; VW 068145702BX; VW 068145703Q; VW 068145704CX; VW 068145704CV; AUDI
068145704CX; AUDI 068145704CV; AUDI 068145703QX; AUDI 068145704C; AUDI 068145703QV; AUDI
068145702B; AUDI 068145703Q; AUDI 068145702BX; AUDI 068145702BV; AUDI 068145703M; SEAT
068145702BV; SEAT 068145702BX; SEAT 068145703QV; SEAT 068145702B; SEAT 068145703M;
SEAT 068145703QX; SEAT 068145704C; SEAT 068145703Q; SEAT 068145704CV; SEAT
068145704CX; SCHLÜTTER TURBOLADER 172-02010; SCHLÜTTER TURBOLADER 17202010; BTS
Turbo T911033; BorgWarner 53149706087; BorgWarner 53149706082; BorgWarner 53149886082;
BorgWarner 53149886087; ALANKO 900770; GARRETT 4665344; GARRETT 4665341; GARRETT
4665343; BE TURBO 124054; BE TURBO 124022; GARRETT 4665345; MOTAIR TURBO 333072



