



Turbos - TUR0069N - TURBO NUEVO 5303-970-0163

Turbo reparado, reconstruido, barato, economico, SsangYong Actyon + 2.0 Xdi [Jan 2006] / SsangYong Kyron 2.0 Xdi [enero de 2006 +], 761433-5003S 761433-0003 761433-0002 761433-3 761433-2

Totalmente remanufacturado (reconstruido, reconstruido, reacondicionado) turbocompresor GARRETT original genuino

761433-5003S 761433-0003 761433-0002 761433-3 761433-2

A6640900880 / A6640900780 / A664 090 08 80 / A664 090 07 80

SsangYong Actyon + 2.0 Xdi [Jan 2006] / SsangYong Kyron 2.0 Xdi [enero de 2006 +]

