

Turbos - TUR0586 - TURBO INTERCAMBIO 10009700113

53049700125, 53049700144, 53049700143, 10009700100, 10009700112, 10009930113, 53049700125, 10009700030, 10009700068, 10009700113, 1000970009, 10009880096, 10009880113, 03L145715B, 03L145701R, 03L14587

53049700125, 53049700144, 53049700143, 10009700100, 10009700112, 10009930113, 53049700125, 10009700030, 10009700068, 10009700113, 1000970009, 10009880096, 10009880113, 03L145715B, 03L145701R, 03L145873A, 03L145873D, 03L145715L, 03L145715K, 03L145873BV, 03L145873CX, 03L145873BX, 03L145715HX, 03L145701SX, 03L145873C, 03L145873B, 03L145701S, 03L145873CV, 03L145715M, 03L145715HV, 03L145715M, 03L145715CX, 03L145715CV, 03L145701SV, 03L145715MX, 03L145715H

Motor: CNEA, CSHA VW Amarok 2011/11-2019/12 2HA, 2HB, S1B, S6B, S7A, S7B 2.0 BiTDI 1968 ccm, 132 KW, 180 PS

Motor: CNEA, CSHA VW Amarok 2011/11-2019/12 2H_, S1B 2.0 BiTDI 4motion 1968 ccm, 132 KW, 180 PS

