

Turbos - TUR0592 - TURBO INTERCAMBIO 784114

784114

784114

784114-0002

784114-0003

784114-5002S

784114-5003S

Específicas Hyundai

28231-2F000

28231-2F001

282312F000

282312F001

Hyundai

Hyundai IX35 2012/01-2015/12 LM 2.0 CRDi 1995 ccm, 135 KW, 184 PS

Hyundai IX35 2010/01-2015/12 LM 2.0 CRDi 4WD 1995 ccm, 135 KW, 184 PS

KIA

KIA Sportage 2010/08-2015/12 SL 2.0 CRDi 1995 ccm, 135 KW, 184 PS

KIA Sportage 2010/08-2015/12 SL 2.0 CRDi AWD 1995 ccm, 135 KW, 184 PS

