

Turbos - TUR0059N - TURBO NUEVO 720855

038253016FX, 038253016F
03G253016QX, 03G253016Q

Garrett

720855-5007S, 7208555007S, 7208555005S, 720855-5006S
7208550001, 7208550003, 7208550004, 7208550005, 7208550006
720855-1, 720855-3, 72085

Audi

Audi A3 8L1 1.9 TDI 2000/08- 1896 ccm, 96 KW, 130 PS
Audi A3 8L1 1.9 TDI quattro 2000/08- 1896 ccm, 96 KW, 130 PS

Seat

Seat Leon 1M1 1.9 TDI 2003/05-2006/06 1896 ccm, 96 KW, 130 PS
Seat Toledo II 1M2 1.9 TDI 2003/05-2006/05 1896 ccm, 96 KW, 130 PS

Skoda

Skoda Octavia 1U2 1.9 TDI 2003/01- 1896 ccm, 96 KW, 130 PS
Skoda Octavia Combi 1U5 1.9 TDI 2003/01- 1896 ccm, 96 KW, 130 PS

VW

VW Bora 1J2 1.9 TDI 2000/11-2005/05 1896 ccm, 96 KW, 130 PS
VW Bora 1J2 1.9 TDI 4motion 2000/11-2005/05 1896 ccm, 96 KW, 130 PS
VW Bora Kombi 1J6 1.9 TDI 2000/11-2005/05 1896 ccm, 96 KW, 130 PS
VW Bora Kombi 1J6 1.9 TDI 4motion 2000/11-2005/05 1896 ccm, 96 KW, 130 PS
VW Golf IV 1J1 1.9 TDI 2000/11-2005/06 1896 ccm, 96 KW, 130 PS
VW Golf IV 1J1 1.9 TDI 4motion 2000/11-2005/06 1896 ccm, 96 KW, 130 PS
VW Golf IV Variant 1J5 1.9 TDI 2000/11-2006/06 1896 ccm, 96 KW, 130 PS
VW Golf IV Variant 1J5 1.9 TDI 4motion 2000/11-2006/06 1896 ccm, 96 KW, 130 PS