

Turbos - TUR0353N - TURBO NUEVO 54399700054

VAG

045253019J, 045253019JV, 045253019JX

Borg Warner

BV39-0054

54399700054, 54399880054

Seat

Seat Cordoba 6L2 1.4 TDI 2005/05-2009/11 1422 ccm, 51 KW, 70 PS

Seat Cordoba 6L2 1.4 TDI 2005/06-2009/11 1422 ccm, 59 KW, 80 PS

Seat Ibiza IV 6L1 1.4 TDI 2005/05-2009/11 1422 ccm, 51 KW, 70 PS

Seat Ibiza IV 6L1 1.4 TDI 2005/06-2009/11 1422 ccm, 59 KW, 80 PS

Seat Ibiza V 6J5 1.4 TDI 2008/07-2010/06 1422 ccm, 59 KW, 80 PS

Seat Ibiza V Sportcoupe 6J1 1.4 TDI 2008/07-2010/06 1422 ccm, 59 KW, 80 PS

Skoda

Skoda Fabia -- 1.4 TDI 2007/01-2010/03 1422 ccm, 59 KW, 80 PS

Skoda Fabia -- 1.4 TDI 2007/02-2010/03 1422 ccm, 51 KW, 70 PS

Skoda Fabia 6Y2 1.4 TDI 2005/10-2008/03 1422 ccm, 51 KW, 70 PS

Skoda Fabia 6Y2 1.4 TDI 2005/10-2008/03 1422 ccm, 59 KW, 80 PS

Skoda Fabia Combi -- 1.4 TDI 2007/10-2010/03 1422 ccm, 51 KW, 70 PS

Skoda Fabia Combi -- 1.4 TDI 2007/10-2010/03 1422 ccm, 59 KW, 80 PS

Skoda Fabia Combi 6Y5 1.4 TDI 2005/10-2007/12 1422 ccm, 51 KW, 70 PS

Skoda Fabia Combi 6Y5 1.4 TDI 2005/10-2007/12 1422 ccm, 59 KW, 80 PS

Skoda Fabia Praktik -- 1.4 TDI 2005/10-2007/12 1422 ccm, 51 KW, 70 PS

Skoda Fabia Stufenheck 6Y3 1.4 TDI 2005/10-2007/12 1422 ccm, 51 KW, 70 PS

Skoda Fabia Stufenheck 6Y3 1.4 TDI 2005/10-2007/12 1422 ccm, 59 KW, 80 PS

Skoda Roomster 5J 1.4 TDI 2006/07-2010/03 1422 ccm, 51 KW, 70 PS

Skoda Roomster 5J 1.4 TDI 2006/09-2010/03 1422 ccm, 59 KW, 80 PS

Skoda Roomster Praktik 5J 1.4 TDI 2007/03-2010/03 1422 ccm, 51 KW, 70 PS

Skoda Roomster Praktik 5J 1.4 TDI 2007/03-2010/03 1422 ccm, 59 KW, 80 PS

VW

VW Polo 9N_ 1.4 TDI 2005/04-2009/11 1422 ccm, 51 KW, 70 PS

VW Polo 9N_ 1.4 TDI 2005/04-2009/11 1422 ccm, 59 KW, 80 PS

