

Turbos - TUR0354N - TURBO NUEVO 49335-01000

1515A185, 1515-A185

MHI Nr.

49335-01000, 4933501000

49335-01001, 4933501001

49335-01002, 4933501002

49335-01003, 4933501003

49T35-01002, 49T3501002

Mitsubishi

MAZDA B2200 (GA_W_) 1.8 DI-D 06.10 - 09.11 85kw 116PS 1798ccm Geländewagen geschlossen

MAZDA B2200 (GA_W_) 1.8 DI-D 06.10 - 06.11 110kw 150PS 1798ccm Geländewagen geschlossen

MAZDA B2200 (GA_W_) 1.8 DI-D 4WD 06.10 - 06.11 110kw 150PS 1798ccm Geländewagen geschlossen

MAZDA LANCER VIII (CY_A, CZ_A) 1.8 DI-D 05.10 - 06.11 85kw 116PS 1798ccm Stufenheck

MAZDA LANCER VIII (CY_A, CZ_A) 1.8 DI-D (CY9A) 05.10 - 06.11 110kw 150PS 1798ccm Stufenheck

MAZDA LANCER VIII Sportback (CX_A) 1.8 DI-D 05.10 - 06.11 85kw 116PS 1798ccm Schrägheck

MAZDA LANCER VIII Sportback (CX_A) 1.8 DI-D (CX9A) 06.10 - 06.11 110kw 150PS 1798ccm Schrägheck

